

U. S. Department of Agriculture
FOREST SERVICE

V16

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 28 W 5th Mer.

S. 1/16 "15.54" + "15 5.27"
Corner common to Sections
27, and 34

Corner consists of a 2" I.M. ~~5/16~~ in place


State condition good

Dimensions above ground 24 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Apparently set by County Engineer.

Arthur T. Johnson
Arthur T. Johnson
(Signature)

Semi-skilled Worker
(Title)

4/4/38
(Date)

V-16

V16

Corner sets in fence line about
 100 feet west of new highway #84 about
 1/2 mile north of Longville.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 141 N. R. 28 W. 5th Mer.

V-16