

U. S. Department of Agriculture

FOREST SERVICE

X17

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 28 W 5th Mer.  
1/4 Corner common to Sections

34, and 35

Corner consists of a cedar post (not) in place  
State condition Fair

Dimensions above ground 18 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4S	Scribing grown over		
B. T.			

Species Cedar Cedar  
Diameter 6" 8"  
Bearing N31<sup>1</sup>/<sub>2</sub>°W N62<sup>1</sup>/<sub>2</sub>°E  
Distance 12 lks. 19 lks.

Do you believe this to be a genuine Land Office Corner? No  
If not, why? Set by County Surveyor.

Arthur T. Johnson  
(Signature)  
Semi-skilled Worker  
(Title)

4/6/38  
(Date)

X-17

alp

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 141 N. R. 28 W. 5th Mer.

X-17