

Form 874-B—Revised May, 1913
U. S. Department of Agriculture
FOREST SERVICE

F18

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY



T. 141 R. 28 Mer.

NW 1/16 Corner common to Sections
11, _____, _____, and _____

Corner consists of a Brass cap (~~mark~~) in place
State condition Good

Dimensions above ground 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Raymond T. Defant
RAYMOND T. DEFANT

Agric. Aide (Signature)
Foreman CCC SP-5

7-31-41 (Date)

(Title)

See Wilson farm

Corner again.

Give any further facts which will aid in finding this


chains distant. 0.25

from which this Corner bears S 70 W

side of tree

tree 5 inches diameter, on the SW

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)