

## U. S. Department of Agriculture

## FOREST SERVICE

Chippewa NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 28 W. 5th Mer.

~~1/4~~ STANDARD  
1/4 ~~corner~~

Corner common to Sections

Corner consists of a 3/4" I.M. ~~rod~~ in placeState condition Set in mound of rock.

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S. 55			
B.T.			

Species J. PineDiameter 12"Bearing N 45° EDistance 116 lbs.Do you believe this to be a genuine Land Office Corner? NOIf not, why? Set by J. A. Gjelhang*Arthur T. Johnson*

Arthur T. Johnson

(Signature)

Semi-skilled Worker

(Title)

4/28/38

(Date)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 24 N. R. 28 W. Mer.

2-19