

U. S. Department of Agriculture
FOREST SERVICE

V19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 28 W 5th Mer.

1/4 Corner common to Sections

26, and 35 post.

Corner consists of a 1" I.M. & brass cap & described in place

State condition good

Dimensions above ground 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

		1/4	
--	--	-----	--

N W S E

1/4	26/35		
-----	-------	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S26- 141- 28	S35- 141- 28		
B.T.	B.T.		

Species Cedar Tam. stub

Diameter 8" 9"

Bearing N49 1/2° W S18° W

Distance 56 lks. 72 lks.

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

Arthur T. Johnson
Arthur T. Johnson

(Signature)

Semi-skilled Worker

(Title)

4/4/38


(Date)

aka

#84.
 corner which is $\frac{3}{4}$ west of highway
 Transit line runs E. & W. thru this
 Corner again.

Give any further facts which will aid in finding this
 chains distant. 0.08

from which this Corner bears
 N57°30'E
 side of tree.
 tree 3 inches diameter, on the Northwest
 Metal Location Poster is on a Tamarack



(Make sketch of topography near Corner)

T. 141 N R. 28 W 5th Mer.

V-19