

U. S. Department of Agriculture

FOREST SERVICE

Chip. Purchase NATIONAL FOREST *1-19*

CORNERS OF THE PUBLIC SURVEY

T. *1A* R. *28* *5<sup>th</sup>* Mer.

*Center 1/4* Corner common to Sections

\_\_\_\_\_ and *1/4*

Corner consists of a *Cedar Post* in place

State condition *Good*

Dimensions above ground *2A* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Tree and Distances in Links.

	<i>SW</i>	<i>SE</i>	

Species *Oak Oak*

Diameter *12" 12"*

Bearing *S25°W S45°E*

Distance *1.90 ch. 1.50 ch.*

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *Indian Service*

*O. Y. Leonard*  
*3/11/35*

(Date)

SECTIONAL CORNER  
SECTIONAL CORNER  
SECTIONAL CORNER

Corner again.

Give any further facts which will aid in finding this

chain distant.


from which this Corner bears

side of

tree 6 inches diameter, on the

Metal Location Poster is on a

Patrol Tree  
North  
State Road  
South



(Make sketch of topography near Corner)