

U. S. Department of Agriculture

FOREST SERVICE

Summary General

Chippewa NATIONAL FOREST

✓
E-19

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 28 5 Mer. Quarter Corner common to Sections

2, and 11



Corner consists of a Br. cap. iron (not) in place State condition Removed from position

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species W. Oak

Diameter 12"

Bearing North

Distance 45.1K

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

D. J. Sutton

(Signature)

Estimator

(Title)

9/5/35
(Date)

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this corner bears *South*

side of *tree*

tree *18* inches diameter, on the *South*

Metal Location Poster is on a *W. Oak*



(Make sketch of topography near corner)