

U. S. Department of Agriculture
FOREST SERVICE

120
3229-37
[Signature]
✓

C-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 28 51A Mer.

e 1/4

Corner common to Sections

2, _____, and _____

Corner consists of a 5" x 5" x 5" (not) in place

State condition Good

Dimensions above ground 42 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Established by Forest Service (C.C.C. crew)

Carl Steadland
(Signature) (Foreman)

July 1936
(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears *Poster is an corner post*

side of

tree inches diameter, on the

Metal Location Poster is on a *corner post*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

C-19

T. 141 N R. 20 W S. 44 Mer.