

## U. S. Department of Agriculture

FOREST SERVICE

X 20

Chippewa NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 28 W 5th Mer.

C. S. 1/16 \* 8 Corner common to Sections

, , , , , ~~xxx~~ 35Corner consists of a 4" Spruce post (~~xxx~~ in place)

State condition new

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

E. 1/16			
S. 35			
B. T.			

Species Birch

Diameter 5"

Bearing S60°E

Distance 13 lks.

Do you believe this to be a genuine Land Office Corner? No.

If not, why? Set by J. A. Gjelhaug

*Arthur T. Johnson*  
 Arthur T. Johnson  
 (Signature)

Semi-skilled Worker

(Title)

5/14/38

(Date)

8-7304

X-20

Op

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 141 N R. 28 W 5th Mer. X-20