

U. S. Department of Agriculture
FOREST SERVICE

V20

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 28 W 5th Mer.

E. 1/16 " / S. 35 Corner common to Sections
_____, _____, 26, and 35

Corner consists of a 1" I.M. & cap (not in place)

State condition good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E	NW	SW	SE	NE

(Note: The 'E' and 'NW' cells in the table are circled, with 'E. 1/16' written in the 'E' cell and '26/35' written in the 'NW' cell.)

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Arthur F. Johnson
Arthur F. Johnson
(Signature)

Semi-skilled Worker
(Title)

4/4/38
(Date)

V-20

U.S.

Corner again. This corner lies 4 chains west of Bullhead lake.


Give any further facts which will aid in finding this chains distant.

from which this Corner bears N6°30'W

side of tree

tree 3 inches diameter, on the North

Metal Location Poster is on a tamarack



(Make sketch of topography near Corner)

T. 141 N

R. 28 W

5th

Mer.

V-20