

U. S. Department of Agriculture
FOREST SERVICE

123
123-37
[Handwritten initials]

DTF
Chippewa NATIONAL FOREST C-20

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 28 5th Mer.

CE 1/16 Corner common to Sections

2, _____, and _____

Corner consists of a 5" aspen post (not) in place

State condition Good

Dimensions above ground 42 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Established by Forest Service (CCC crew)


Carl Stedland
(Signature) (Tennison)

July 1936
(Date)

(Title)

17-10-76 L. Willhoft Cor 15
 in a wet marsh no evidence of
 CCC post or tag

Corner again.
 Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears *later on corner post*
 side of
 tree inches diameter, on the
 Metal Location Poster is on a *corner post*



(Make sketch of topography near Corner)

C-20
Mer.

T. 141 N. R. 28 W. 5th