

U. S. Department of Agriculture

FOREST SERVICE

X21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 28 W 5th Mer.

1/4

Corner common to Sections

35, and 36

Corner consists of a cedar post (not) in place

State condition good - just put in.

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S.35			
B. T.			

Species W.Pine

Diameter 7"

Bearing N14°40'W

Distance 50 1/2 lks.

Do you believe this to be a genuine Land Office Corner? no.

If not, why? Set by J. A. Gjalhaug.

Arthur T. Johnson
(Signature)

Semi-skilled Worker
(Title)

5/14/38

(Date)

X-21

[Handwritten initials]

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 141 N. R. 28 W. 5th Mer. X-21