

U. S. Department of Agriculture
FOREST SERVICE

Posted 5-21

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 141 R. 28 Mer.

Section 4 Corner common to Sections
11, 12, 13, and 14.

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

*T 141
R 28
S 13*

*T 141
R 28
S 11*

137

Species N.PINE N.PINE

Diameter 29" 29"

Bearing S 45° E E 90°

Distance 50' 10 1/2'

Do you believe this to be a genuine Land Office Corner?

If not, why? _____

G. Sherman

(Signature)

ENGINEER

(Title)

3/16/35

(Date)

J-21

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree 27 inches diameter, on the North

Metal Location Poster is on a *Beetling tree*



(Make sketch of topography near Corner)

Mer. T-21

T. 141 R. 28