

U. S. Department of Agriculture
FOREST SERVICE

170
7-29-36
H. C. [Signature]

B-21

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 141 R. 28 Mer. 500
N 1/16 Corner common to Sections

1, 2, and

Corner consists of a 4" x 3/4" x 1/2" post (net) in place

State condition good

Dimensions above ground 4.2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Established by Forest Service

Carl Steadland
(Signature) (Foreman)

July 1936
(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.57

from which this Corner bears *S 84 E*

side of

tree inches diameter, on the

Metal Location Poster is on a *corner post*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mer.

T. 101 N. R. 28 W. 5th

B-21