

U. S. Department of Agriculture
FOREST SERVICE

127
7-29-37
[Signature]

C-22

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 28 5th Mer.

C.W. 416

Corner common to Sections

1, _____, and _____

Corner consists of a 5" oak post (not) in place

State condition Good

Dimensions above ground 4.2 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? Established by Forest

Service (see crew)

Carl Steadland
(Signature) (Tennison)

July 1936
(Date)

Metal Location Poster is on a *corner post*
 tree inches diameter, on the
 side of
 from which this Corner bears *840 E*
 chains distant. *0.14*
 Give any further facts which will aid in finding this
 Corner again.

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

6-22

E. W. R. R. 200
Mer.