

U. S. Department of Agriculture
FOREST SERVICE

B-22

123
7-29-21
[Signature]

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 28 S. 5th Mer.

NW 1/4 Corner common to Sections

1, and

Corner consists of a 4" *respon. post* (not) in place


State condition *good*

Dimensions above ground *42* inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *Established by Forest*

Service (e.c.a. crew)

Carl Steadland
(Signature)

July 1936
(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears *Poster on corner post*

side of

tree inches diameter, on the

Metal Location Poster is on a *the corner post*

458A

		Sec.	Sec.
		Sec.	Sec.

(Make sketch of topography near Corner)

B-22

Mer.

546

R. 28 N.

T. 107 N.