

Form 874-B—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Procting-23

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 141 R. 58 Mer.

1/4 Corner common to Sections
12, and 13

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S
12

1/4 S
11

BT

BT

Species Oak Oak _____

Diameter 12" 24" _____

Bearing SSW N85E _____

Distance 2 ch 2 ch _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

G. Sherman
(Signature)

3/10/35
(Date)

Engineer
(Title)

Corner again.


Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

Metal Location Poster is on a **DARK B. T.** tree **74** inches diameter, on the **EAST**



(Make sketch of topography near Corner)

Mer. J-23

T. 141 R. 24