

U. S. Department of Agriculture
FOREST SERVICE

128
7-29-37
[Signature]

F
Chippewa NATIONAL FOREST

F23

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 28 5 Mer.

CN 1/16 Corner common to Sections

12, _____, and _____

Corner consists of a 1" iron pipe w/ brass cap ~~rod~~ in place

State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	No B. T.s.		

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? _____

H. E. Altman
H. E. ALTMAN
(Signature)

6/9/36
(Date)

Assistant Ranger
(Title)

F-48

C.L.R.

62-5.0.

south of corner.

of corner. Hay Meadow lies 4 chains

Fence corner is 4/10 chains west

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



Makes sketch of topography near Corner

T 141

R

28

5

Mer.

F-23