

U. S. Department of Agriculture

FOREST SERVICE

S.D.
J24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 28 S. Mer.

1/32 1/20th. W. of E 1/16 Corner common to Sections

12, 13, and

Corner consists of a 1" iron pipe w/ brass cap. in place

State condition Good

Dimensions above ground 5 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

3.12		
<u>Tr. 1691</u>		
AP		
12/109		
N	W	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and all blanks below, giving bearings from Corner to Trees and Distances in Links.

	No	B. Ts.	

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why?

H. E. Altman

H. E. ALTMAN

(Signature)

Assistant Ranger

(Title)

6/1/36


(Date)

J-23-24 2-7394

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant.

Give any further facts which will aid in finding this Corner again.

CORNER IN AN SANDY GROUND 10 feet NORTH OF NORTH EDGE OF ROAD.



(Make sketch of topography near Corner)