

U. S. Department of Agriculture

FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 28/27 5th Mer.

1/4 Corner common to Sections

25, and 30
Corner consists of a Pipe and Cap in place


State condition Good

Dimensions above ground 6 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

O. J. Pearson
(Signature)

3/18/25
(Date)

Eng
(Title)

Corner again.
The Corner location
Poster on South side of
Road at the corner
19.9 chains South of
1/4 25/30.

Give any further facts which will aid in finding this


~~chains distant.~~

~~from which this Corner bears~~

~~side of~~ ~~at the Corner,~~

~~tree~~ ~~inches diameter,~~ ~~on the~~ ~~Directly~~

Metal Location Poster is on a Corner Forest Post.



(Make sketch of topography near Corner)

T. 141 R. 28/27 5th T-25 Mer.