

U. S. Department of Agriculture
FOREST SERVICE

122
7-27-37
[Handwritten signature]

B-21-22
Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141* R. *28* *5th* Mer.

1/4 N-10 chs. W of N 1/4 Corner common to Sections
1, *2*, and

Corner consists of a *5" aspen post* (not) in place
State condition *Good*

Dimensions above ground *42* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *Established by Forest Service (C.C.C. crew)*

Carl Steadland
(Signature) (Tennison)

July 1936
(Date)

(Title)

[Faint, mostly illegible text in the top section of the page]

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.04

from which this Corner bears 584 W

side of

tree inches diameter, on the

Metal Location Poster is on a 6" aspen

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Met.

R. 28 W

T. 141 N

B-2122