

U. S. Department of Agriculture

FOREST SERVICE

YZ 18 19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 28 W 5th Mer.

Reservation Corner common to Sections

-----, -----, ~~rock~~ ----- 35

Corner consists of a 3" spruce post ~~(rock)~~ in place


State condition New

Dimensions above ground 48 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

I.R.B.			
B.T.			

Species B. Spruce

Diameter 4"

Bearing N80°W

Distance 24½ lks.

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Set by J. A. Gjelhaug.

Arthur T. Johnson

Arthur T. Johnson

(Signature)

5/14/38

(Date)

Semi-skilled Worker

(Title)

XZ-18,19

147

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.	35	Sec.

(Make sketch of topography near Corner)

T. 141 N R. 28 W 5th Mer.

42-18,19