

U. S. Department of Agriculture

FOREST SERVICE

122
7-29-37
PP

K-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141 N* R. *79 W* *5* Mer.

C N 1/16 Corner common to Sections *18*, _____, and _____

Corner consists of a *1" I.P. W/cap* (not) in place


State condition *Good*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *R. Oak*

Diameter *2.0*

Bearing *S 69 E*

Distance *9.7*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

G. C. Upham

4/5/1937
(Date)

G. C. Upham
(Title) *K-3*

Corner again.

Give any further facts which will aid in finding this

chain distant.

from which this corner bears

N 1/4 W


side of

D.N. 1/2

tree 10 inches diameter, on the

Metal Location Poster is on a

Howson



(Make sketch of topography near corner)

R-3
Mer

T. L. N. B. 29W