

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 29 W 5 Mer.

5 Sec. Corner common to Sections
5, 6, 7, and 8

Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>S</u> <u>8</u>			
<u>B.T.</u>			

Species OAK (Stump 11/10)

Diameter 9"

Bearing S(?)E

Distance 1/2 ch

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

H. M. ...
(Signature)

ENGINEER

(Title)

3/14/35
(Date)

E-5

Corner again.

Give any further facts which will aid in finding this

chains distant.


from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

None



(Make sketch of topography near Corner)

T 141N R 29W

5-

Mer

E-5