

U. S. Department of Agriculture  
FOREST SERVICE

123/07  
7-29-07  
L-10  
4

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141 N* R. *29 N* *5th* Mer.

*CW* Corner common to Sections *16* and

Corner consists of a *1" I.P.W. Cap* (net) in place


State condition *Good*

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*1/14/37* (Date) *R. Moore* (Signature) *Asst. Dir. - F. D. S.* (Title) *L-10*

Corner again.

Give any further facts which will aid in finding this

chain distant.

0.76

From which this Corner bears

0.31 E

side of

tree 1 1/4 inches diameter, on the

Metal Location Poster is on a

*OK*


◆ Sec 6

(Make sketch of topography near Corner)

Mar. 1-10

524

R 79

T 141N