

U. S. Department of Agriculture

FOREST SERVICE

123
7-29-36
P

Chippewa NATIONAL FOREST J-10

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 29 W 5th Mer.

N¹/₁₆ Corner common to Sections
9, and 16

Corner consists of a 1" I.M.W. brass cap (not) in place


State condition Good

Dimensions above ground 14" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadland

(Signature)

June 29 1936
(Date)

Const. For
(Title)

J-10

Corner again.

Give any further facts which will aid in finding this

0.60 chains distant.

from which this Corner bears

S78W

side of

tree inches diameter, on the

Metal Location Poster is on a

Copy

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T-10

Mer.

29

R

T 141