

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

1231
7-29-37
[Signature]

Chippewa NATIONAL FOREST

L-11

CORNERS OF THE PUBLIC SURVEY

T. *141N* R. *29W* *5th* Mer.

C/4

Corner common to Sections

16

and

Corner consists of a *1" I.M. with brass cap* (not) in place


State condition *Good*

Dimensions above ground *7"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of *1* is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why?

Carl Steadland

(Signature)

July 24 1936

(Date)

Const. For.

(Title)

L-11

Corner again.

Give any further facts which will aid in finding this

chains distant,

from which this Corner bears

side of

at corner

feet inches diameter, on the

Corner post
Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mer. L-11

T. 111 R. 29