

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

122
7-29-37
K-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141 N.* R. *29 W.* *5th* Mer.

Q N 1/16 Corner common to Sections
16, _____, and _____


Corner consists of a *1" I.M. with brass cap* (not) in place
State condition *Good*

Dimensions above ground *12* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Carl Steadland

(Signature)

Const. Loc.

(Title)

July 24, 1936

(Date)

K-11

Corner again.

Give any further facts which will aid in finding this

obtain distant.

from which this Corner bears

side of *at corner*

tree *H* inches diameter, on the

Aspen tree
Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mer 1-11

T 141 R 29