

U. S. Department of Agriculture

FOREST SERVICE

172
7-29-37
[Signature]

K-12

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 79 W 5th Mer.

NE 1/16 Corner common to Sections 16, and


Corner consists of a 4" Red Oak Post (not) in place State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why?

Established by CCC crew

July 28 1936 (Date)

[Signature] Const (Title) for K-12

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

*1.16
S 78 W*

side of

tree 7.0 inches diameter, on the

Metal Location Poster is on a

Post

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

R-12
Mer.

T. 141 R. 29