

U. S. Department of Agriculture

FOREST SERVICE

123
2-29-37
N-13
[Signature]

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 29 W. S. 12 Mer.

Corner common to Sections 15, 16, 21, and 22

Corner consists of a 2" IM. Brass Cap (set) in place

State condition Good

Dimensions above ground 8" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E





NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

[Signature] (Signature)

July 1936 (Date)

Const. Exp. (Title)

N-13

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears *532 E*

side of

tree *10* inches diameter, on the

Metal Location Poster is on a *Norway Pine*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

N-13

Mer.

29

R.

141

T.