

U. S. Department of Agriculture

FOREST SERVICE

*Chippewa*

NATIONAL FOREST

173  
7-29-37  
L-13  
2

CORNERS OF THE PUBLIC SURVEY

T. *14N* R. *29W* *5<sup>th</sup>* Mer.

Corner common to Sections

*14*, *15*, and *16*

Corner consists of a *4" Rock post* (not) in place



State condition *Good*

Dimensions above ground *36"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *No*

If not, why?

*Established by CCC crew*

*Paul Steadland*

(Signature) *Const. Fore.*

*July 28, 1936*  
(Date)

(Title)

L-13

Corner again.

Give any further facts which will aid in finding this

chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on *Corner post*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mer. 7-13

T 141 R 29