

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

F72
[Handwritten initials]

Chippewa NATIONAL FOREST *Q-15*

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 29W 5th Mer.

C.S. 116 Corner common to Sections
22, and


Corner consists of a 4" Aspen Post (net) in place
State condition Good

Dimensions above ground 3 1/2 Ft inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? No

If not, why? _____

Established by CCC Crew

Carl Steadland

(Signature)

July 1936

(Date)

Corst. For.

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant. 0.30

from which this Corner bears N 53 W

side of

tree .5 inches diameter, on the

Metal Location Poster is on a White Pine



(Make sketch of topography near Corner)

T. 141 N R. 24 W Mer. Q-15