

U. S. Department of Agriculture  
FOREST SERVICE

123  
7-29-37  
[Signature]

L-15

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *14 N.* R. *29 W.* *5<sup>th</sup>* Mer.



Corner common to Sections *15*, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a *1" I.M. with brass cap* (not) in place  
State condition *Good*

Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

*July 1936*  
Date

*Carl Stendrup*  
(Signature)  
*Const. For.*  
(Title)

L-15

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

*None*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mer. 7-15

T. 141 R. 29