

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Q-18
122
729
37
W
Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141 N* R. *29 W* *5th* Mer.
S.W. *1/16* Corner common to Sections

.....,, *23*, and

Corner consists of a *4" Oak Post* (not) in place
State condition *Good*

Dimensions above ground *3 1/2 Ft* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

N	W	S	E

DIAGONAL POSITION

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? *No*

If not, why?

Established by C.C.C. Crew.

Carl Steadland
(Signature)

July 1936
(Date)

Const. For
(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

121

from which this Corner bears

S 21 E

side of

tree *H* inches diameter, on the

Metal Location Poster is on a *White Oak*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mer. Q-18

T. 141 R. 29