

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY *1 of 2*

T. *141N* R. *29W* *5th* Mer.

4 Corner common to Sections
23, and *26*

Corner consists of a *Brass pipe* (not) in place
State condition *good*

Dimensions above ground *8"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|-------------|--|--|--|
| <i>None</i> | | | |
| | | | |

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Daniel Rose Jr

(Signature)

Estimator

(Title)

April 5 35

(Date)

Corner again.

Give any further facts which will aid in finding this


26.3 755, distant.

from which this Corner bears N 90 E

side of 5700

12. inches diameter, on the NE

Metal Location Posters on a Pine stub



(Make sketch of topography near Corner)

Mer. R-19

T. 191N R. 29W

5

U. S. Department of Agriculture

FOREST SERVICE

WJA

Chippewa NATIONAL FOREST

Partial R-19 2 of 2

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 20 W. Sth. 5th. Mer.

1/4 Corner common to Sections

23, and 26

Corner consists of a I.M. & Brass Cap in place

State condition Good

Dimensions above ground 8" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | | | | | |
|---|---|------------|-----------|----|----|----|----|
| | | <u>1/4</u> | <u>23</u> | | | | |
| | | | <u>26</u> | | | | |
| N | W | S | E | NW | SW | SE | NE |

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|--|--|--|
| | | | |
| | | | |

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Arthur J. Johnson
(Signature)

1/20/38

(Date)

Semi Skilled Worker

(Title)

R-19

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

287
R-19
Mer