

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

123
7-29-37
H. E. T.
✓
P

Chippewa NATIONAL FOREST

P-19

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 29 W 5th Mer.
C 1/4

Corner common to Sections
23, _____, _____, and _____



Corner consists of a 1 1/2" Brass Cap (not) in place
State condition Good

Dimensions above ground 6" 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Carl Steadland

(Signature)

Co. 175th For.

(Title)

July 24, 1936
(Date)

P-19

Corner again.

Give any further facts which will aid in finding this


chains distant. 0.23

From which this Corner bears 551W

side of

tree 8 inches diameter, on the

Metal Location Poster is on a Spruce



(Make sketch of topography near Corner)

Mer. P-19

T 141 R 29