

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

Chippewa

NATIONAL FOREST

L-22

R

CORNERS OF THE PUBLIC SURVEY

T. *141 N.* R. *29 W.* *5th* Mer.

CW 1/16 Corner common to Sections

13, _____, and _____

Corner consists of a *1" I.M. with brass cap* (not) in place



State condition *Good*

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Carl Steadland
(Signature)

July 1936
(Date)

Const. Fore.
(Title)

subject to paragraph 2, 11

100

SECTIONAL CORNER

SECTIONAL CORNER

Corner again.

Give any further facts which will aid in finding this

chains distant.

100

from which this Corner bears

0 7/10 W

side of

tree 6 inches diameter, on the

Metal location Poster is on *See Date*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

7-22

Mer.

B. 029

141

T