

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

172
7-21-27
M-24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *14* R. *29* S. *5th* Mer.
SE 1/16 Corner common to Sections

13, and

Corner consists of a *3" Birch post* (not) in place

State condition *Good*

Dimensions above ground *36* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? _____

Established by CCC crew

Carl Steadland

(Signature)

Const. For

(Title)

July 1936

(Date)

Stationed at ...

...

4

...

...

...

Corner again.

Give any further facts which will aid in finding this

chain distant.

From which this Corner bears *N 38° E*

side of

tree *12* inches diameter, on the

Metal Location Poster is on a *P. Pine*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

M-24
Mer.

T 141 N R 29 W 57 E