

U. S. Department of Agriculture

FOREST SERVICE

123
7-29-37
[Signature]

Chippewa

K₂L-11

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *141 N* R. *29 W* S. *5* Mer.

1/64

Corner common to Sections

16 - located 9.36 ch. N. of C 1/4 Sec. 16

Corner consists of a *1" I.M. with house* (not) in place



State condition *Good*

Dimensions above ground *1* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Carl Steadland

(Signature)

Const. Sur.

(Title)

July 24 1936

(Date)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of ~~at~~ *at corner*

tree ⁵ inches diameter, on the

Apex post
Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T 141 R 20 W 5th Mer. K.L-11