

U. S. Department of Agriculture  
FOREST SERVICE

123  
7-29-37  
*[Signature]*

*Chippewa*

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *14 N.* R. *29 W.* *5th* Mer.

*1/6 S* Corner common to Sections  
*22 - located 10.08 ch. S of N<sup>1/2</sup> E<sup>1/2</sup> Corner*, and

Corner consists of a *1" I.M. with brass cap* (not) in place



State condition *Good*

Dimensions above ground *2"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? \_\_\_\_\_

*Carl Steadland*

(Signature)

*Const. For*

(Title)

*July 28, 1936*

(Date)

Corner again.

Give any further facts which will aid in finding this

chain distant.

from which this Corner bears

*550 E*

side of

tree inches diameter, on the

Metal Location Poster is on a

*Copier*

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

Mer.

*T 141 N R 29 W 5th*

*0 P-20*