

U. S. Department of Agriculture  
FOREST SERVICE

R, 5-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 29 W 5th Mer.

Reservation Corner common to Sections

26, and 27

Corner consists of a 1" I.M. & brass cap (not) in place


State condition good

Dimensions above ground 4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S27	S26		
141-	141-		
29	29		
B.T.	B.T.		

Species R. Pine R. Pine

Diameter 12" 14"

Bearing N39°W N22°E

Distance 54 lks. 21 lks.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*Arthur E. Johnson*  
Arthur E. Johnson  
(Signature)  
Semi-skilled Worker  
(Title)

3/23/38  
(Date)

R-5-17 *etc*

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

R-5-17

Mer.

5th

R. 29 W

T. 141 N