

Form 874-9—Revised May, 1913
U. S. Department of Agriculture
FOREST SERVICE

*already
Painted*

*FILED
S. O. #304
A1*

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141-142 R. 30-31 5 Mer.

Section Corner common to Sections

36, 31, 6 and 1 w/brass cap

Corner consists of a 2" iron pipe ~~set~~ in place

State condition Good

Dimensions above ground 3 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	No	B.	Ts.	

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? _____

H. E. Altman
H. E. ALTMAN

Assistant Ranger

9/14/36

(Date)

(Title)