

U. S. Department of Agriculture
FOREST SERVICE

Handwritten initials
K2

CHIPPewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 30 W 5th Mer.

N. W 1/6 Corner common to Sections 18, _____, and _____


Corner consists of a IRON PIPE, BRASS CAP (not) in place
State condition GOOD: shows above water in slough.

Dimensions above ground 18 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Arthur J. Johnson
(Signature)
Asst. to Forester
(Title)

(Date)

Metal Location Poster is on a tree _____ inches diameter, on the side of _____ from which this Corner bears _____ chains distant.

Give any further facts which will aid in finding this Corner again.

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. 141 R. 30 Mer. K-2