

U. S. Department of Agriculture

FOREST SERVICE

*WJL*

J 2

CRIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 30 5<sup>th</sup> Mer.

N 1/6 Corner common to Sections  
7, and 18

Corner consists of a 2" IRON PIPE, CAP (not) in place  
State condition GOOD

Dimensions above ground 10" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? YES

If not, why? \_\_\_\_\_

*Arthur J. Johnson*

(Signature)

12/9/37  
(Date)

*Semi-Skilled Worker*  
(Title)

ON THE SOUTH SIDE OF ROAD

Corner again.

Give any further facts which will aid in finding this


0.53 chains distant.

from which this Corner bears N. 56. E.

side of

tree inches diameter, on the

Metal Location Poster is on a ASPEN



(Make sketch of topography near Corner)

T. 121 R. 20 S. 36 M&T. T-2