

U. S. Department of Agriculture

FOREST SERVICE

Chippewa

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N. R. 30 W. 5th Mer.

1/16

Corner common to Sections

and



Corner consists of a 1" IN W/BRASS CORNER in place

State condition GOODDimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|--|--|--|
| | | | |
| | | | |

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Arthur T. Johnson
ARTHUR T. JOHNSON

(Signature)

Semi Skilled Worker

(Title)

2/9/38

(Date)

CORNER IS 20 CHAINS EAST OF
T. 1. 45th JUST SOUTH OF CORNER I-48.
CORNER 45th IS A FORMER CORNER.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 141 N. R. NO. 1. 5th Mer.

B-2