

Form 874-0—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

[Handwritten initials]

T 4

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 30 W 5th Mer.

CE 1/4 Corner common to Sections
30, and

Corner consists of a 2" GALV. I. P. (net) in place
State condition Good

Dimensions above ground LAYING ON GROUND inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

Species
Diameter
Bearing
Distance

Do you believe this to be a genuine Land Office Corner? NO

If not, why? PROBABLE COUNTY CORNER

John A. March
(Signature) *DEPT.*
7/27/37 (Date) *Jr. Asst. to Tech*
(Title)

NORTH AND SOUTH

CORNER ON FENCE LINE RUNNING

Corner again.

Give any further facts which will aid in finding this


0.27 chains distant.

from which this Corner bears S 150° W

side of

tree 6 inches diameter, on the

Metal Location Poster is on a TAMMACK



(Make sketch of topography near Corner)

T. 141

R. 30

S. 77

T-4 MET.