

U. S. Department of Agriculture
FOREST SERVICE

Wick
V5

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *14 N.* R. *30 W.* *5* Mer.

Corner common to Sections

29, 30, 31, and 32

Corner consists of *2" I.P.* (not) in place


State condition *Good*

Dimensions above ground *16* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *County Corner*

Carl E. Steadland

(Signature)


Foreman F-48

(Title)

6/9/37
(Date)

Corner again.
Lot 4. Post 36" above ground
at corner

Give any further facts which will aid in finding this
0.32 chains distant.
from which this Corner bears
N75W
side of
5 inches diameter, on the
Metal Location Poster is on a
Post



(Make sketch of topography near Corner)

T. 14 N. R. 30 W. 5th V-S Mer.