

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

J5

CHIPPEWA..... NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 N R. 30W 5th Mer.

SECTION..... Corner common to Sections

7, 8, 17, and 18

Corner consists of a 2" IRON PIPE (set) in place

State condition GOOD

Dimensions above ground 12" ABOVE WATER 1/4 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of..... is located.....

Pits are located.....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species.....

Diameter.....

Bearing.....

Distance.....

Do you believe this to be a genuine Land Office Corner? YES

If not, why?.....

Arthur T. Johnson

(Signature)

Levi Shilled Weber

(Title)

12/6/37  
(Date)

ALONG ROAD

Corner again.

Give any further facts which will aid in finding this


chains distant.

55  
from which this Corner bears S 86° E

side of

tree 5 inches diameter, on the

Metal Location Poster is on an ASPEN



(Make sketch of topography near Corner)

T. 141 R. 90 S. 77 Mer. T-S