

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST *E 9*

CORNERS OF THE PUBLIC SURVEY

T. *141N* R. *30W* Mer. *5*

Corner common to Sections

4, *5*, *8*, and *9*

Corner consists of a *Iron stake* in place



State condition *Leaning to S-E*

Dimensions above ground *19* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____ *Downy Junco*
Diameter _____ *1 1/4*
Bearing _____ *N. 28° E*
Distance _____ *1.54*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

Francis Heinrich

(Signature)

Estimator

(Title)

March 18

(Date)

Corner again.

Give any further facts which will aid in finding this

chain distant.


from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

post



(Make sketch of topography near Corner)

5-9 M.G.

T. L. H. N. R. 30 W.