

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST *Posted* N11

CORNERS OF THE PUBLIC SURVEY

T. 141N R. 30W 5 Mer.

44 Corner common to Sections  
16, and 21

Corner consists of a \_\_\_\_\_ (not) in place  
State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and  
fill blanks below, giving bearings from Corner to Trees and  
Distances in Links.

SEC 14 16			
B.T.			

Species N. PINE  
Diameter 13"  
Bearing N(?)  
Distance 40'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_


*H. M. ...*  
(Signature)  
ENGINEER  
(Title)

3/18/35  
(Date)

Corner again.

Give any further facts which will aid in finding this  
chains distant.  
from which this Corner bears  
side of  
tree inches diameter, on the  
Metal Location Poster is on a

*NONE*



(Make sketch of topography near Corner)

T. 141 N. R. 30 W. 5 Mer. N-11